

From: [Miller, Garyg](#)
To: [Paul R Schroeder \(Paul.R.Schroeder@erdc.dren.mil\)](mailto:Paul.R.Schroeder@erdc.dren.mil)
Cc: [Earl Hayter](#); [Sanchez, Carlos](#); [Foster, Anne](#)
Subject: FW: San Jacinto River Maintenance Workplan
Date: Friday, October 6, 2017 7:43:12 AM
Attachments: [San Jacinto - Letter to Miller at EPA_10052017.pdf](#)

Paul,

Please see the attached work plan & let me know if you see any revisions needed to secure the cap.

Also, is it possible that the change from the cap's rock bottom to the riverbed sediment bottom is creating turbulence that may be encouraging erosion of the sediment near the cap?

Thanks,

Gary Miller
Remedial Project Manager
EPA Region 6 Superfund Division, TX/Ark Section
214-665-8318
miller.garyg@epa.gov

From: John Laplante [<mailto:jlaplante@anchorqea.com>]
Sent: Thursday, October 05, 2017 5:56 PM
To: Miller, Garyg <Miller.Garyg@epa.gov>
Cc: David Keith <dkeith@anchorqea.com>; John Verduin <jverduin@anchorqea.com>; Wendell Mears <wmears@anchorqea.com>; David Moreira <dmoreira@wm.com>; Phil Slowiak <philip.slowiak@ipaper.com>; Judy Armour (jarmour@wm.com) <jarmour@wm.com>
Subject: San Jacinto River Maintenance Workplan

Gary –

Attached please find the workplan for maintenance in the San Jacinto River Channel adjacent to the TCRA armored cap. Let us know if you have questions or comments.

Hard copies are being sent via FedEx.

Regards,

John Laplante, P.E.
Anchor QEA, LLC
720 Olive Way Suite 1900
Seattle, WA 98101

Office: 206.287.9130
Direct: 206.903.3323
Fax: 206.287.9131
Mobile: 206.795.2676